## FIELD INSPECTION REPORT

		4.12.2020	District: Muppy	
Division: Mrs. pr Esect -2			Length (km): 3.420	
		25.507 to A	rakwe Lakharpu	rvR-10
	Programme:	MAINTENANCE		
Packag	e No.: of the Project:	0 1 10 1 1	Road Id No.:	
	s a case of:	Ongoing/Completed		
SI. No.			p gradation/ Maintenance	
	Parameters to be checked			Remarks
1.	Pavement			
a)	Road Junction condition			S/U
b)	Condition of Surfacing			\S/U
c)	Riding Quality			√S/U
d)	Road Camber			S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
f)	Contraction Joints provided or not (CC Pavement)			· Yes/No
g)	Compaction of flank/slope & raincuts if any			Yes/No
2.	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
c)	Condition of railings/slab/approach for Bridges			S/SRI/U
3.	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No
4.	Compliance History			
a)	Status of ATR's	& any others		

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

This Row is Roodefeeted.

This Row is Roodefeeted.

The Row is Roodefeeted.

(Signature)

NAME: - Umeshpagwan
DESIGNATION: - Turniv Engiraen.