

FIELD INSPECTION REPORT

Date of Inspection :	District: <u>Muzaffarpur</u>	
Division : <u>Muz. East-2</u>	Length (km): <u>0.745 km</u>	
Name of the Road: <u>Lot - Lot 5 Dharampur Banghara, PWD road to Barchman to Hanka</u>		
Scheme/Programme:	MAINTENANCE	
Package No.: <u>BR-23 R-460</u>	Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance	
Work is a case of:	New Connectivity/Up gradation/ Maintenance	
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	<u>S/U</u>
b)	Condition of Surfacing	<u>S/U</u>
c)	Riding Quality	<u>S/U</u>
d)	Road Camber	<u>S/U</u>
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	<u>S/SRI/U</u>
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	<u>S/SRI/U</u>
c)	Condition of railings/slab/approach for Bridges	<u>S/SRI/U</u>
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)

NAME: Bachy

DESIGNATION: 18112120