FIELD INSPECTION REPORT

-		8-12-20	District: Myzefferpus		
Division: R. W. D. Mus. West-			Length (km).	Length (km).	
	of the Road:	ailal Sall ke	Ghas co Poul On	Bendlet	
Packag		MAINTENAN	CE	20,77200 16	
The Property of	of the Project:	10-1 10	Road Id No.2		
Work is a case of:		Ongoing/Completed/Under Maintenance New Connectivity/Up gradation/ Maintenance			
SI. No.	The same of the sa	Thew Connectiv	ity/Up gradation/ Maintenance		
02100	Parameters to be checked			Remarks	
1.	Pavement				
a)	Road Junction condition			8/U	
b)	Condition of Surfacing			S/U	
c)	Riding Quality			₩.S/U	
d)	Road Camber			√S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No	
f)	Contraction Joints provided or not (CC Pavement)			Yes/No	
g)	Compaction of flank/slope & raincuts if any			Yes/No	
2,	Cross Drains	ge is			
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			%/SRI/U	
c)	Condition of railings/slab/approach for Bridges			S/SRI/U	
3.	Road Furnitu	re			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			₩es/No	
42	Compliance H	istory			
a)	Status of ATR'	s & any others		No	

Overall Rating

Satisfactory (S)	101
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)

NAME: Ajay Chandlery-

DESIGNATION: A E