

FIELD INSPECTION REPORT

Date of Inspection : 16.12.2020		District : Munger
Division : Munger		Length (km):
Name of the Road : Eakasi Tola pul to prem daba Astham		
Scheme/Programme : MAINTENANCE NABARD		
Package No.:		Road Id No.: SN - 335
Status of the Project:	Ongoing/Completed/Under Maintenance	
Work is a case of :	New Connectivity/Up gradation/Maintenance	
Sl.No.	Parameters to be checked	Remarks
1	Pavement	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓ Yes / No
f)	Contraction Joints provided or not(CC Pavement)	✓ Yes / No
g)	Compaction of flank/slope & raincuts if any	✓ Yes / No
2	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓ S/ SRI / U
b)	Condition of Abutment & Wing walls Slab in Rcc culverts - N/A	S/ SRI / U
c)	Condition of railings/slab/approach for Bridges - N/A	S/ SRI / U
3	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes / No
4	Compliance Histroy	
a)	Status of ATR's & any others - बाढ़ प्रभावित सड़क	

Overall Rating :

Satisfactory (S)	✓
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME :

DESIGNATION :

Boyle
16/12/2020
(Signature)
malerla
A. E.