

FIELD INSPECTION REPORT

Date of Inspection : 16-12-2020 District: BANKA
 Division : BANKA-2 Length (km): 0.895
 Name of the Road: Darta chandravandi Tola to Rupsa Sinhnah main Road (MMGSY, GEN)
 Scheme/Programme: MAINTENANCE, 1st year
 Package No.:
 Status of the Project: Ongoing/Completed/Under Maintenance ✓ Road Id No.: 20703601209
 Work is a case of: New Connectivity/Up gradation/ Maintenance ✓

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓ Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓ Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No ✓
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U ✓
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U ✓
c)	Condition of railings/slab/approach for Bridges	S/SRI/U ✓
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	—
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	—

Au
 16-12-2020
 (Signature)

NAME: AJAY KUMAR
 DESIGNATION: AE