

FIELD INSPECTION REPORT

Date of Inspection : 17/12/20	District: Nalanda
Division : Rajgir	Length (km): 0.230 km.
Name of the Road: L034 To Mahadeobigha	
Scheme/Programme: MAINTENANCE	MMUSY (GEN)
Package No.:	Road Id No.:
Status of the Project:	☒ Ongoing/ ☐ Completed/ ☐ Under Maintenance ongoing
Work is a case of:	☒ New Connectivity/ ☐ Up gradation/ ☐ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	☒ S/U
b)	Condition of Surfacing	☒ S/U
c)	Riding Quality	S/U
d)	Road Camber	☒ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/ ☒ No
f)	Contraction Joints provided or not (CC Pavement)	☒ Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U (N/A)
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U (N/A)
c)	Condition of railings/slab/approach for Bridges	S/SRI/U (N/A)
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	☒ Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Rampresh Kumar
JE.
NAME: Rajgir

17/12/20
JE
(Signature)