

FIELD INSPECTION REPORT

Date of Inspection : 17.12.2020	District: Malanda
Division : Ha Ray 218	Length (km): 0.430
Name of the Road: Same Mar 54a Inayatpur to Sidhiksha	
Scheme/Programme: MAINTENANCE	M.M.G.S.Y (H)
Package No.:	Road Id No.:
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No X
f)	Contraction Joints provided or not (CC Pavement)	Yes/No X
g)	Compaction of flank/slope & raincuts if any	Yes/No ✓
2.	Gross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓ S/SR/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SR/U
c)	Condition of railings/slab/approach for Bridges	✓ S/SR/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRi)	—
Unsatisfactory (U)	—

[Signature]
17.12.2020
(Signature)

NAME: Shiva Prakash Gukh

DESIGNATION: A.E. (Pen)