

FIELD INSPECTION REPORT

DATE OF INSPECTION :		DISTRICT	SUPAUL
DIVISION TRIVENIGANJ		LENGTH (Km)	2.15 KM
NAME OF ROAD : L 051 - T 03 To Karkara (VR18)			
SCHEME PROGRAMME		MAINTENANCE	
PACKAGE NO. BR 35 R 155		Road Id No. :	
STATUS OF PROJECT :		ONNGING/COMPLETED/UNDER MAINTENANCE	
Work is a case of :		New Connectivity/ Up gradation/Maintenance	
Sl. No.	PARAMETERS TO BE CHECKED		REMARKS
1	PAVEMENT		
a	Road junction condition		✓S/U
b	Condition of Surface		✓S/U
c	Riding Quality		✓S/U
d	Road Camber		✓S/U
e	Whether free from defectssuch as visible cracks exposed aggregates in case of CC pavement		✓Yes/No
f	Construction Joints provided or not (CC Pavement)		✓Yes/No
g	Compaction of flank/ Slope & Rain cuts if any		✓Yes/No
2	Cross Drainage		
a	Condition of head walls in Hume pipe culverts including its painting		S/SRI/U
b	Condition of abutment & Wing walls, Slab in RCC culverts		✓S/SRI/U
c	Condition of railings/slab/approach for Bridges		✓S/SRI/U
3	Road Furniture		
a	Whether sign boards/informatory/cautionary Board/ km & 200m stones/ Pavment road markings are provided and maintained		✓Yes/No
3	Compliance History		
a	Status of ATR's & any Others		Yes/No

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement	
Unsatisfactory (U)	

Surendra Kumar
S.D.O RWD
Chhatrapur
Name

Surendra
16/12/20
Signature