FIELD INSPECTION REPORT

Date of In	spection: 16/12/20	District: Rohlan		
Division: Delvy		Length (km):		
Name of		Judimi Janewali Phil Road to Mahua	21 Bigha	
	rogramme: MAINTENAN	NCE	0	
Package No.: Road Id No.:				
Status of the Project: Ongoing/Completed/Under Maintenance				
Work is a case of: New Connectivity/Up gradation/ Maintenance				
Sl. No.	Parameters to be checked P		Remarks	
1.	Pavement			
a)	Road Junction condition		_S/U	
b)	Condition of Surfacing		_S/U	
c)	Riding Quality	< S/U		
d)	Road Camber	∠ S/U		
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			
f)	Contraction Joints provided or not (CC Pavement) Yes/No			
g)	Compaction of flank/slope & raincuts if any			
2.	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting			
b)	Condition of Abutment & Wing walls, Slab in RCC culverts > S/SRI/U			
c)			- S/SRI/U	
3.	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained Yes/No			
4	Compliance History			
a)	Status of ATR's & any other	ers		

Overall Rating

Satisfactory (S)	5
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)

NAME: Om Brokash Kuman

DESIGNATION: JE

Scanned with CamScanner