

FIELD INSPECTION REPORT

Date of Inspection : 13-12-2020		District: BANKA	
Division : BANKA-2		Length (km): 0.35	
Name of the Road: Bhagatpur Handiha Main Road To Dhoni Railway Station (NAWARD)			
Scheme/Programme: MAINTENANCE, 1st Year			
Package No.:			
Status of the Project:			
Work is a case of:		Road Id No.: 2070360030013	
		New Connectivity/Up gradation/ Maintenance	
Sl. No.	Parameters to be checked		Remarks
1.	Pavement		
a)	Road Junction condition		S/U
b)	Condition of Surfacing		S/U
c)	Riding Quality		S/U
d)	Road Camber		S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		Yes/No
f)	Contraction Joints provided or not (CC Pavement)		Yes/No
g)	Compaction of flank/slope & raincuts if any		Yes/No
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting		S/SR/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SR/U
c)	Condition of railings/slab/approach for Bridges		S/SR/U
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		Yes/No
4.	Compliance History		
a)	Status of ATR's & any others		

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	S
Unsatisfactory (U)	

NAME: AJAY KUMAR
DESIGNATION: AB

13-12-2020
(Signature)