

perpanti

FIELD INSPECTION REPORT

Date of Inspection: 17/12/2020		District: Bhagalpur	
Division: Kahlgaon		Length (km):	
Name of the Road: PMWS Gobindpur to Narayanpur Road to Kukur Singh tola.			
Scheme/Programme: MAINTENANCE		MMWSY (GEN)	
Package No.:		Road Id No.:	
Status of the Project: Ongoing/Completed/Under Maintenance		Under Maintenance	
Work is a case of: New Connectivity/Up gradation/Maintenance			
Sl. No.	Parameters to be Inspected		
1.	Pavement		
a)	Road Junction condition	S/U	S
b)	Condition of Surfacing	S/U	S
c)	Riding Quality	S/U	S
d)	Road Camber	S/U	S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	Yes
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	
g)	Compaction of Bank/slope & raincuts if any	Yes/No	No
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SR/U	S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SR/U	N
c)	Condition of railings/slab/approach for Bridges	S/SR/U	NA
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No	Yes
4.	Compliance History		
i)	Status of AFR's & any others		No

Overall Rating:

Satisfactory (S)	S
Satisfactory but requires Improvement (SR)	
Unsatisfactory (U)	

By 17/12/2020
(Signature)

NAME: