

FDR 2020 Reported

pirparuti

FIELD INSPECTION REPORT

Date of Inspection:	17/12/2020	District:	Bhagalpur
Division:	Kahalgau	Length (km):	2.311 Km
Name of the Road:	NH-80 to Kamaal Dhorai		
Scheme/Programme:	MAINTENANCE MMASY(SC)		
Package No.:		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	S/S	S
b)	Condition of Surfacing	S/U	U
c)	Riding Quality	S/U	U
d)	Road Camber	S/S	NA
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	NA
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	NA
g)	Compaction of flank/slope & raincuts if any	Yes/No	Yes
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SR/U	NA
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SR/U	NA
c)	Condition of railings/slab/approach for Bridges	S/SR/U	NA
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No	No
4.	Compliance History		
i)	Status of AFR's & any others		No

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SR)	
Unsatisfactory (U)	U

Damaged in 2020 Flood. put A not required.

Signature
(Signature)

NAME: