

### FIELD INSPECTION REPORT

Date of Inspection: 05/12/2020		District: Sheikhpura
Division: Sheikhpura		Length (km): 0.600 KM
Name of the Road: Barbigha Mehur Road to Dumtu		
Scheme/Programme: MAINTENANCE (On going)		Road Id No.:
Package No.:		Status of the Project: <input checked="" type="checkbox"/> Ongoing/ <input type="checkbox"/> Completed/ <input type="checkbox"/> Under Maintenance
Work is a case of:		<input checked="" type="checkbox"/> New Connectivity/ <input type="checkbox"/> Up gradation/ <input type="checkbox"/> Maintenance
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	S/U NA
a)	Road Junction condition	S/U NA
b)	Condition of Surfacing	S/U NA
c)	Riding Quality	S/U NA
d)	Road Camber	S/U NA
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No NA
f)	Contraction Joints provided or not (CC Pavement)	Yes/No NA
g)	Compaction of flank/slope & raincuts if any	Yes/No NA
2.	Cross Drainage	S/SRI/U NA
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U NA
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U NA
c)	Condition of railings/slab/approach for Bridges	S/SRI/U NA
3.	Road Furniture	Yes/No
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	<input checked="" type="checkbox"/> Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

yet to be done.

Overall Rating :	Satisfactory (S)	S
	Satisfactory but requires Improvement (SRI)	—
	Unsatisfactory (U)	—

05/12/2020  
 (Signature)

NAME: SANGRAM HEMBRDM  
 DESIGNATION: A.E.