## FIELD INSPECTION REPORT

|                        |  | FIELD INSPEC  | HON REPORT             |          |
|------------------------|--|---|------------------------|----------|
| Date of Inspection:    |  |   | District: Gobsgant     |          |
| Division: Gobalgant -1 |  |   | Length (km): 2.46      |          |
|                        | f the Road?  | Madhobrath to                                       | Bangalphand            |          |
|                        | Programme:   | MAINTENANCE   | 0 1                    |          |
|                        |  |   | Road Id No.:           |          |
|                        |  |   | eted/Under Maintenance |          |
| Work is a case of:     |  | New Connectivity/Up gradation/ Mainténance  Remarks |                        |          |
| Sl. No.                | 图 数人的特别  | Parameters to b                                     | e checked              | Remarks  |
| ı                      | Payement   |   |                        |          |
| a)                     | Road Junction condition  |   |                        | LSAU     |
| b)                     | Condition of Surfacing   |   |                        | CS/U     |
| c)                     | Riding Quality   |   |                        | , S/U    |
| - d)                   | Road Camber  |   |                        | S/U      |
| e)                     | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. |   |                        | Yes/No   |
| f)                     | Contraction Joints provided or not (CC Pavement)   |   |                        | Yes/No   |
| g)                     | Compaction of flank/slope & raincuts if any  |   |                        | Yes/No   |
| 2.                     | Cross Drainage   |   |                        |          |
| a)                     | Condition of head walls in Hume pipe culverts including its painting                         |   |                        | S/SRI/U  |
| b)                     | Condition of Abutment & Wing walls, Slab in RCC culverts                                     |   |                        | \S/SRI/U |
| c)                     | Condition of railings/slab/approach for Bridges  |   |                        | \S/8RI/U |
| 3.                     | Road Furnitu   | ire   |                        |          |
| a)                     | Whether sign boards/informatory/cautionary Board/km & 200m                                   |   |                        |          |

Overall Rating

a)

4.

a)

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

Boll 20 20

Compliance History

Status of ATR's & any others

(Signature)

NAME:

AJAY KUMR TINARI

stones/Pavement road markings are provided and maintained

**DESIGNATION:** 

E.E.