

FIELD INSPECTION REPORT

Date of Inspection : 04.12.2020
 Division : NARCATIA GAY
 District : WEST CHAMPARAN
 Name of the Road : Betia Land Road Srisiga Adda To Azad chowk
 Length (km):
 Scheme/Programme: MAINTENANCE
 Package No.: RM/WE/NAR/19/0003
 Road Id No.: 3/808908041
 Status of the Project: Ongoing/Completed/Under Maintenance
 Work is a case of: New Connectivity/Up gradation/ Maintenance ✓

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	
b)	Condition of Surfacing	Ongoing
c)	Riding Quality	✓
d)	Road Camber	✓
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓
f)	Contraction Joints provided or not (CC Pavement)	NA
g)	Compaction of flank/slope & raincuts if any	NA
2.	Cross Drainage	NO
a)	Condition of head walls in Hume pipe culverts including its painting	NA
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	NA
c)	Condition of railings/slab/approach for Bridges	NA
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Ongoing
4.	Compliance History	
a)	Status of ATR's & any others	—

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	—
Unsatisfactory (U)	—

[Signature]
 04/12/2020
 (Signature)

NAME: JAY PR. AKASH RAM

DESIGNATION: JF