FIELD INSPECTION REPORT

Date of	Inspection: (04-19-20 Dist	trict: Gobalgan		
Division		Goodgary- Len	gth (km): 5730	wayra Indarwa Barra	m.
	f the Road:	have Barkagar	rvillage to mulcular	14avra Indarua Baira Shuke	ug
	Programme:	MAINTENANCE	TYTAL		
Package No.: Status of the Project: Ongoing/Completed			d Id No.:		
	a case of:	New Connectivity/Up gra			
Maria Carlos Company	a case of.	Remarks			
Sl. No.	Parameters to be checked Remarks				
i.	Payement VII (S)				
a)	Road Junction condition			\$/U (S)	
b)	Condition of Surfacing			S/U (U)	
c)	Riding Quality			S/U (U)	
d)	Road Camber			\s/u (\frac{1}{2})	
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No Yes	
f)	Contraction Joints provided or not (CC Pavement)			Yes/No	
g)	Compaction of flank/slope & raincuts if any			Yes/No Ny Yair	1CV
2.	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U H A	
c)	Condition of railings/slab/approach for Bridges			S/SRI/U HA	
3	Road Furniture				
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No (Yes)	
4.	Compliance H	istory			
a)	Status of ATR's & any others			NOATR	
Overall I	Rating :	(0)			

Satisfactory (S)	•	
Satisfactory but requires Improvement (SRI)	-	
Unsatisfactory (U)		
Unsatisfactory (0)		_

(Signature)

NAME: Ajoy kumor Tiward

DESIGNATION: Executive Engineeror