


FIELD INSPECTION REPORT

Date of Inspection : 08.12.2020	District: 10. Champaran
Division : Narkatiaganj	Length (km): 14.50 km
Name of the Road: Mathura to Pidari	
Scheme/Programme: MAINTENANCE	
Package No.: MR3054	Road Id No.: 3180890 8059
Status of the Project: Ongoing/Completed/Under Maintenance	Under maintenance
Work is a case of:	New Connectivity/Up gradation/ Main nance maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S S/U
b)	Condition of Surfacing	S S/U
c)	Riding Quality	S S/U
d)	Road Camber	S S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	NA Yes/No
f)	Contraction Joints provided or not (CC Pavement)	NA Yes/No
g)	Compaction of flank/slope & raincuts if any	NA Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	NA S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	NA S/SRI/U
c)	Condition of railings/slab/approach for Bridges	NA S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	—

Overall Rating : S

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	


 08/12/20
 (Signature)

NAME: Chandradas Pd
 DESIGNATION: JE