

# FIELD INSPECTION REPORT

|                                                                                         |                          |
|-----------------------------------------------------------------------------------------|--------------------------|
| Date of Inspection : 09.12.2020                                                         | District: W. Champaran   |
| Division : Markatiyaganj                                                                | Length (km): 6.50 km     |
| Name of the Road: Repair of pucca bitum. maintained road to margadwa via Gauripur Baran |                          |
| Scheme/Programme: MAINTENANCE                                                           |                          |
| Package No.: MR 3054                                                                    | Road Id No.: 31808908064 |
| Status of the Project: Ongoing/Completed/Under Maintenance                              | Under Maintenance        |
| Work is a case of: New Connectivity/Up gradation/ Maintenance                           | Maintenance              |

| Sl. No. | Parameters to be checked                                                                                             | Remarks |
|---------|----------------------------------------------------------------------------------------------------------------------|---------|
| 1.      | <b>Pavement</b>                                                                                                      |         |
| a)      | Road Junction condition                                                                                              | S       |
| b)      | Condition of Surfacing                                                                                               | S       |
| c)      | Riding Quality                                                                                                       | S       |
| d)      | Road Camber                                                                                                          | S       |
| e)      | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.                         | -       |
| f)      | Contraction Joints provided or not (CC Pavement)                                                                     | -       |
| g)      | Compaction of flank/slope & raincuts if any                                                                          | -       |
| 2.      | <b>Cross Drainage</b>                                                                                                |         |
| a)      | Condition of head walls in Hume pipe culverts including its painting                                                 | -       |
| b)      | Condition of Abutment & Wing walls, Slab in RCC culverts                                                             | -       |
| c)      | Condition of railings/slab/approach for Bridges                                                                      | -       |
| 3.      | <b>Road Furniture</b>                                                                                                |         |
| a)      | Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained | S       |
| 4.      | <b>Compliance History</b>                                                                                            |         |
| a)      | Status of ATR's & any others                                                                                         | -       |

Overall Rating :

|                                             |   |
|---------------------------------------------|---|
| Satisfactory (S)                            | S |
| Satisfactory but requires Improvement (SRI) | - |
| Unsatisfactory (U)                          | - |

(Signature) 09/12/20

NAME: Chandradas Prasad

DESIGNATION: JE