

# FIELD INSPECTION REPORT

Date of Inspection : 03/12/2020		District: West Champaran
Division : Narkatiyaganj		Length (km): 4.430
Name of the Road: Purshetampur se Madhuri		
Scheme/Programme: MAINTENANCE		
Package No.: MR 3054 old	Road Id No.: 31808900836	
Status of the Project:	Ongoing/Completed/Under Maintenance	
Work is a case of:	New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	- S -
b)	Condition of Surfacing	- S -
c)	Riding Quality	- S -
d)	Road Camber	- S -
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	
f)	Contraction Joints provided or not (CC Pavement)	
g)	Compaction of flank/slope & raincuts if any	
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	- S -
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	
c)	Condition of railings/slab/approach for Bridges	
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	- S -
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	- S -
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME: Chandradev Prasad  
DESIGNATION: Junior Engineer

(Signature) 3/12/20