FIELD INSPECTION REPORT

Date of	Inspection: 19	-12-2020 Di	strict: - hopalgani	
Division: R. M. D. hopalami - 1			Length (km): 1-10 K-M	
Name of	f the Road: N		use of Heera Thakur vic	a Brahmastha
	/Programme:	MAINTENANCE L		
Package No.:			Road Id No.: /Under Maintenance -	
1023 M No. 1	a case of:	New Connectivity/Up gr		· · · · · · · · · · · · · · · · · · ·
Sl. No.	Parameters to be checked		Remarks	
1.	Pavement			
a)	Road Junction condition			S/U
b)	Condition of Surfacing			\$/U
c)	Riding Quality			STÚ
d)	Road Camber		'S/U	
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/NoL
f)	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts if any			Yes/No~
2.	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U N
c)	Condition of railings/slab/approach for Bridges			S/SRI/U N
3.	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No
4.	Compliance History			
a)	Status of ATR's & any others			NO ATR

Satisfactory (S)	(5)
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME: Dinesh prosed

DESIGNATION: J.E. 18/12/2020