		FIELD INSPE	CTION REPORT		
Date of Inspection-		17-12-20	District Pata	9	
Division-		Patra	Length (KM)		
Vame o	f Road-	Bhilwara mah	adalit Tola to Pa	rsa Sampetch	
Scheme/Programme-		Patra Length (KM)  Bhilwara mahadalib Tola to Parsa .  Pmusy Read  Road Id No.			
Package	e no		Road Id No.		
Status of the Project			/Under Maintenance		
Work is a case of		New Connectivity/Up gradation/Maintenance			
sl no.		Parameters to	be Checked Remarks		
1	Pavement				
а	Road Junction Condition			S/U	
b	Condition of Surfacing			S/U	
С	Riding Quantity			S/U	
d	Road Camber			S/U	
е	Whether free from defects such as visible cracks, exposed aggregates in			s in Yes/No	
	case of CC Pavement				
f	Contraction joints provided or not (CC Pavement)			Yes/No	
g	Compaction of flank/slope & raincuts if any  Yes/No				
2	Cross Drainage				
а	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U	
b	Condition of Abutment & Wing walls, Slab in RCC Culverts			S/SRI/U	
С	Condition of railings/slab/approach for Bridges S/SRI/L				
3	Road Furniture				
а	Whether sign board/informatory/cautionary Board/KM & 200 m			Yes/No V	
	stones/Pavement road markings are provided and maintained				
4	Compliance History				
а	Status of ATR's	& any others			
	Overall Rating:				
		Satisfactory (S)		-	
		Satisfactory but requ	ires Improvement (SRI)	SRI	
		Unsatisfactory (U)		-	
Note	11-1. Notice	issued to cont	soctor.	A 1	
	2. only Pot	issued to controlled are de recement. wor Pandey	one after	Signature C.E-2	
	Name	0. 1			
	c 1	war lander			
	Et. Yogean				