


FIELD INSPECTION REPORT

Date of Inspection-	18-12-2020	District	Patna
Division-	masaurhi	Length (KM)	2.40
Name of Road-	Musnaper Masaurhi Road to Telhara		
Scheme/Programme-	Maintenance New ✓		
Package no.-	MR-M/19 masaurhi/01	Road Id No.	
Status of the Project	On going/Complete/Under Maintenance		
Work is a case of	New Connectivity/Up gradation/Maintenance ✓		
sl no.	Parameters to be Checked	Remarks	
1	Pavement		
a	Road Junction Condition	✓ S/U	
b	Condition of Surfacing	✓ S/U	
c	Riding Quantity	✓ S/U	
d	Road Camber	✓ S/U	
e	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	Yes/No	} NA
f	Contraction joints provided or not (CC Pavement)	Yes/No	
g	Compaction of flank/slope & raincuts if any	Yes/No ✓	
2	Cross Drainage		
a	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	} NA
b	Condition of Abutment & Wing walls, Slab in RCC Culverts	S/SRI/U	
c	Condition of railings/slab/approach for Bridges	S/SRI/U	
3	Road Furniture		
a	Whether sign board/informatory/cautionary Board/KM & 200 m stones/Pavement road markings are provided and maintained	Yes/No ✓	
4	Compliance History		
a	Status of ATR's & any others	—	

Overall Rating:

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	—
Unsatisfactory (U)	—

Note:- work on Flank is in progress.


 Signature
 C.E-2

Name

Mr. Yageshwar Pandey
 CE-2