FIELD INSPECTION REPORT

Deta	CT.			•
Date of Inspection: 18-12-2020			District: KATIHAR	
Division: KATIHAR.			Length (km): 5.0	
	of the Road: K	olsi to sema	pur road part-c	?
Scheme/Programme: MAINTENANCE Package No.:			· .	
Noad Id 110.: \$110510 8079				
West			ed/Under Maintenance	
SINO E CASE OF		New Connectivity/Up gradation/ Maintenance		
			occhecked #	Remarks
	Payement			
a)	Road Junction condition			8/U
b)	Condition of Surfacing			√S/U
c)	Riding Quality			√8/U
d)	Road Camber			<i>≫</i> /U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
<u>f)</u>	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts if any			Yes/No
2,	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			-S/SRI/U
c)	Condition of railings/slab/approach for Bridges			-S/SRI/U
3.	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No
4. 7.	Compliance Hist	ory		
a)	Status of ATR's & any others			
11.5				

Overall Rating

Satisfactory (S)	
	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)

NAME: Kamush chambhany

DESIGNATION: e. & . >