		FIELD INSPEC	TION REPORT	
Date of Inspection-		17-12-2020	District Patya	
Division-		Patra	Length (KM) 2·33	
Name of Road-		Parsa sampateh	alc PMGISY Rd to Khies	elpur sa
Schemo	e/Programme-	Maintenance V	New New	Khud
Package no		Road Id No.		
Status of the Project		On going/Complete/Under Maintenance		
Work is a case of		New Connectivity/Up gradation/Maintenance		
sl no.		Parameters to b	pe Checked	Remarks
1	Pavement			
а	Road Junction Condition			S/U
b	Condition of Surfacing			S/U
С	Riding Quantity		S/U	
d	Road Camber			S/U
е	Whether free from defects such as visible cracks, exposed aggregates in			Yes/No
	case of CC Pavement			
f	Contraction joints provided or not (CC Pavement)		Yes/No	
g	Compaction of flank/slope & raincuts if any Yes/No			
2	Cross Drainage			
а	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U
b	Condition of Abutment & Wing walls, Slab in RCC Culverts			S/SRI/U
С	Condition of railings/slab/approach for Bridges S/			S/SRI/U
3	Road Furniture			
а	Whether sign board/informatory/cautionary Board/KM & 200 m			Yes/No ~
	stones/Paveme			
4	Compliance History			
а	Status of ATR's	& any others		4 1 7 7

Overall Rating:

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SR1
Unsatisfactory (U)	-

Hote: - 1. Notice issued to contractor.

2. Work not Started after agreement only some both were patched.

Name

Signature C.E-2

Er. Yogeshwar Pandey
CE-2