

## FIELD INSPECTION REPORT

Date of Inspection-	17-12-20	District	Patna
Division-	Patna	Length (KM)	1.01 KM
Name of Road-	Pipra More PMGSY Rd to chatna via chatna maladalit Tola		
Scheme/Programme-	Maintenance ✓		
Package no.-			Road Id No.
Status of the Project	On going/Complete/Under Maintenance		
Work is a case of	New Connectivity/Up gradation/Maintenance ✓		
sl no.	Parameters to be Checked		Remarks
<b>1</b>	<b>Pavement</b>		
a	Road Junction Condition		S/U
b	Condition of Surfacing		S/U
c	Riding Quantity		S/U
d	Road Camber		S/U
e	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement		Yes/No
f	Contraction joints provided or not (CC Pavement)		Yes/No
g	Compaction of flank/slope & raincuts if any		Yes/No
<b>2</b>	<b>Cross Drainage</b>		
a	Condition of head walls in Hume pipe culverts including its painting		S/SRI/U
b	Condition of Abutment & Wing walls, Slab in RCC Culverts		S/SRI/U
c	Condition of railings/slab/approach for Bridges		S/SRI/U
<b>3</b>	<b>Road Furniture</b>		
a	Whether sign board/informatory/cautionary Board/KM & 200 m stones/Pavement road markings are provided and maintained		Yes/No ✓
<b>4</b>	<b>Compliance History</b>		
a	Status of ATR's & any others		

work  
not  
started

Overall Rating:

Satisfactory (S)	-
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	-

Notes:- 1. Notice issued to contractor  
2. work yet to be started

Name

Er. Yogeshwar Pandey

Signature  
C.E-2  
17-12-20