		FIELD INSPECTI	ON REPORT	
Date of Inspection-		17-12-20	District Patna	
Division-			Length (KM) 2.2 KM  Se Achechak Dhamaul path	
Name of Road-		chhatne more	e se Acheclak I	hamaul
Scheme/Programme-		Maintenance		
Package no		Road Id No.		
Status of the Project		On going/Complete/Under Maintenance		
Work is a case of		New Connectivity/Up gradation/Maintenance		
si no.	Parameters to be Checked Remarks			Remarks
1	Pavement			
а	Road Junction Condition S/U/.			
b	Condition of Surfacing S/U			S/U/S
С	Riding Quantity S/U			S/U / S
d	Road Camber VS/U			<b>V</b> 5/U
е	Whether free from defects such as visible cracks, exposed aggregates in Yes/No case of CC Pavement			
f				Yes/No
g				Yes/No ,
2	Cross Drainage			
а	Condition of head walls in Hume pipe culverts including its painting S/SRI			S/SRI/U
b	Condition of Abutment & Wing walls, Slab in RCC Culverts			S/SRI/U
С				S/SRI/U
3	Road Furniture			
а	Whether sign board/informatory/cautionary Board/KM & 200 m			Yes/No
		ent road markings are prov	ided and maintained	
4	Compliance His			
а	Status of ATR's	& any others		

Overall Rating:

Satisfactory (S)	-	
Satisfactory but requires Improvement (SRI)	SR1	
Unsatisfactory (U)	_	

Note: - Pot patch work in Progress.

Signature C.E-2

Name

Er. Yogeshwar Pandey CE-2