

## FIELD INSPECTION REPORT

Date of Inspection-	17-12-20	District	Patna
Division-	Patna	Length (KM)	5.0 KM
Name of Road-	Thaichak More to Achhechak more via Laxmichak Baruna Path		
Scheme/Programme-	Maintenance		
Package no.-	✓	Road Id No.	
Status of the Project	On going/Complete/Under Maintenance		
Work is a case of	New Connectivity/Up gradation/Maintenance ✓		
sl no.	Parameters to be Checked	Remarks	
1	<b>Pavement</b>		
a	Road Junction Condition	S/U	
b	Condition of Surfacing	S/U	
c	Riding Quantity	S/U	
d	Road Camber	S/U	
e	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	Yes/No	
f	Contraction joints provided or not (CC Pavement)	Yes/No	
g	Compaction of flank/slope & raincuts if any	Yes/No	
2	<b>Cross Drainage</b>		
a	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	
b	Condition of Abutment & Wing walls, Slab in RCC Culverts	S/SRI/U	
c	Condition of railings/slab/approach for Bridges	S/SRI/U	
3	<b>Road Furniture</b>		
a	Whether sign board/informatory/cautionary Board/KM & 200 m stones/Pavement road markings are provided and maintained	Yes/No ✓	
4	<b>Compliance History</b>		
a	Status of ATR's & any others		

Work in Progress

Overall Rating:

Satisfactory (S)	—
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	—

Note:- 1. Notice issued to contractor to expedite the work.  
2. Work in Progress

Signature 17-12-20  
C.E-2

Name

Er. Yogeshwar Pandey  
CE-2