

## FIELD INSPECTION REPORT

Date of Inspection-	17-12-20	District Patna
Division- Patna	Patna	Length (KM) 1.0 KM
Name of Road-	Sheikhpura se saidanichak via Pipra path	
Scheme/Programme-	Maintenance ✓ Head 3059	
Package no.-	Road Id No.	
Status of the Project	On going/Complete/Under Maintenance	
Work is a case of	New Connectivity/Up gradation/Maintenance ✓	
sl no.	Parameters to be Checked	Remarks
1	<b>Pavement</b>	
a	Road Junction Condition	S/U ✓
b	Condition of Surfacing	S/U ✓
c	Riding Quantity	S/U ✓
d	Road Camber	S/U ✓
e	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	Yes/No NA
f	Contraction joints provided or not (CC Pavement)	Yes/No NA
g	Compaction of flank/slope & raincuts if any	Yes/No ✓
2	<b>Cross Drainage</b>	
a	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U ✓
b	Condition of Abutment & Wing walls, Slab in RCC Culverts	S/SRI/U ✓
c	Condition of railings/slab/approach for Bridges	S/SRI/U ✓
3	<b>Road Furniture</b>	
a	Whether sign board/informatory/cautionary Board/KM & 200 m stones/Pavement road markings are provided and maintained	Yes/No ✓
4	<b>Compliance History</b>	
a	Status of ATR's & any others	


Overall Rating:

Satisfactory (S)	—
Satisfactory but requires Improvement (SRI)	—
Unsatisfactory (U)	✓

Note:-

1. Notice issued to contractor.
2. Rd damaged in Flood in 2019.
3. FDR is entered in MIS.
4. Work not started.
5. Yogeshwar Pandey

CE-2

  
 Signature 17.12.20  
 C.E-2