

FIELD INSPECTION REPORT

Date of Inspection-	17-12-20	District	Patna
Division-	Patna	Length (KM)	5.1 KM
Name of Road-	NH 30 (old) Aadiapur se Bhuski Tak Patl		
Scheme/Programme-	Maintenance ✓		
Package no.-		Road Id No.	
Status of the Project	On going/Complete/Under Maintenance ✓		
Work is a case of	New Connectivity/Up gradation/Maintenance ✓		
sl no.	Parameters to be Checked		Remarks
1	Pavement		
a	Road Junction Condition		S/U ✓
b	Condition of Surfacing		✓S/U
c	Riding Quantity		✓S/U
d	Road Camber		✓S/U
e	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement		Yes/No ✓
f	Contraction joints provided or not (CC Pavement)		Yes/No ✓
g	Compaction of flank/slope & raincuts if any		Yes/No ✓
2	Cross Drainage		
a	Condition of head walls in Hume pipe culverts including its painting		S/SRI/U
b	Condition of Abutment & Wing walls, Slab in RCC Culverts		S/SRI/U
c	Condition of railings/slab/approach for Bridges		S/SRI/U
3	Road Furniture		
a	Whether sign board/informatory/cautionary Board/KM & 200 m stones/Pavement road markings are provided and maintained		Yes/No ✓
4	Compliance History		
a	Status of ATR's & any others		-


Overall Rating:

Satisfactory (S)	-
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	-

Note:- 1. Pot Patch work in progress
 2. Grass cutting is being done
 3. Heavy Traffic on Road.

Name

Er. Yogeshwar Pandey
 CE-2


 17-12-20
 Signature
 C.E-2