

FIELD INSPECTION REPORT

Date of Inspection-	18-12-2020	District	Patna
Division-	mesaurhi	Length (KM)	4.5 KM
Name of Road-	T03 - Pipla		
Scheme/Programme-	Maintenance New ✓		
Package no.-	Road Id No.		
Status of the Project	On going/Complete/Under Maintenance ✓		
Work is a case of	New Connectivity/Up gradation/Maintenance ✓		
sl no.	Parameters to be Checked	Remarks	
1	Pavement		
a	Road Junction Condition	✓ S/U	
b	Condition of Surfacing	S/U/SRI	
c	Riding Quantity	S/U	
d	Road Camber	S/U	
e	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	Yes/No	
f	Contraction joints provided or not (CC Pavement)	Yes/No	
g	Compaction of flank/slope & raincuts if any	Yes/No ✓	
2	Cross Drainage		
a	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U ✓	
b	Condition of Abutment & Wing walls, Slab in RCC Culverts	S/SRI/U	
c	Condition of railings/slab/approach for Bridges	S/SRI/U	
3	Road Furniture		
a	Whether sign board/informatory/cautionary Board/KM & 200 m stones/Pavement road markings are provided and maintained	Yes/No ✓	
4	Compliance History		
a	Status of ATR's & any others		

Overall Rating:

Satisfactory (S)	-
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	-

Note - 1. Notice issued to contractor
2. Work not started.

Name

Er. Yogeshwar Pandey
CE-2

Signature
C.E-2

25/12/2020