| | | FIELD INSPECT | ION REPORT | | |
|-----------------------|--|--|------------------------------------|---------|--|
| Date of Inspection- | | 18.12.2020 | District Patna | | |
| Division- | | Masawshi | District Patra Length (KM) 4.0 KM | | |
| Name of Road- | | LO34 to Bira | | | |
| Scheme/Programme- | | Maintenance New V | | | |
| Package | e no | | Road Id No. | | |
| Status of the Project | | On going/Complete/Under Maintenance | | | |
| Work is | a case of | New Connectivity/Up g | gradation/Maintenance | | |
| sl no. | | Parameters to b | oe Checked | Remarks | |
| 1 | Pavement | | | 1 | |
| а | Road Junction Condition | | | S/U | |
| b | Condition of Surfacing | | | -\$/U | |
| С | Riding Quantity | | | √S/U | |
| d | Road Camber | | S/U | | |
| е | Whether free f | Whether free from defects such as visible cracks, exposed aggregates in Yes/No | | | |
| | case of CC Pavement | | | | |
| f | Contraction joints provided or not (CC Pavement) | | Yes/No | | |
| g | Compaction of flank/slope & raincuts if any Yes/No | | | | |
| 2 | Cross Drainage | | | | |
| а | Condition of flead wans in flame pipe carrets merasing | | | S/SRI/U | |
| b | Condition of Abutment & Wing walls, Slab in RCC Culverts | | | S/SRI/U | |
| С | Condition of ra | ailings/slab/approach for | Bridges | S/SRI/U | |
| 3 | Road Furniture | | 11/01 | | |
| а | Whether sign board/informatory/cautionary Board/KM & 200 m Yes/No | | | | |
| | stones/Pavement road markings are provided and maintained | | | | |
| 4 | Compliance H | istory | | | |
| | Chatus of ATD | s & any others | | | |

Overall Rating:

| Satisfactory (S) | S |
|---|---|
| Satisfactory but requires Improvement (SRI) | - |
| Unsatisfactory (U) | - |

Note: - 20 m R) under dispute.

Signature C.E-2

Name Er. Yogeshwar Pandey
CE-2