

FIELD INSPECTION REPORT

Date of Inspection : 18/12/2020	District: Samastipur
Division : Dalsingh Jaran	Length (km): 2.724 km
Name of the Road: NH-28 Gangapur se Morwa Prakhanda Talu	
Scheme/Programme: MAINTENANCE	New Maintenance
Package No.:	Road Id No.:
Status of the Project: Ongoing/Completed/Under Maintenance ✓	
Work is a case of: New Connectivity/Up gradation/ Maintenance ✓	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	— S/U
b)	Condition of Surfacing	— S/U
c)	Riding Quality	— S/U
d)	Road Camber	— S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	— Yes/No
f)	Contraction Joints provided or not (CC Pavement)	— Yes/No
g)	Compaction of flank/slope & raincuts if any	— Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	— S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	— S/SRI/U
c)	Condition of railings/slab/approach for Bridges	— S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	— Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	N A

Overall Rating :

Satisfactory (S)	X
Satisfactory but requires Improvement (SRI)	X
Unsatisfactory (U)	U

The completion period has been expired. The contractor has not started the surface course. Action against contractor as per MBD clause has been given.

Samir Kumar
(Signature) 18/12/2020

NAME: SAMIR KUMAR

DESIGNATION: E.E