

# FIELD INSPECTION REPORT

Date of Inspection : 18.12.2020		District: NALANDA	
Division : Rajgir		Length (km): 2.850km	
Name of the Road: SH-31 Kaptipada More to Kaptipada via Bhojpur			
Scheme/Programme: MAINTENANCE		Not Maintained by - 2018, 19	
Package No.:		Road Id No.:	
Status of the Project:		Ongoing/Completed/Under Maintenance <input checked="" type="checkbox"/>	
Work is a case of:		New Connectivity/Up gradation/ Maintenance <input checked="" type="checkbox"/>	
SL No.	Parameters to be checked		Remarks
1.	Pavement		
a)	Road Junction condition		S/U S
b)	Condition of Surfacing		S/U S
c)	Riding Quality		S/U S
d)	Road Camber		S/U S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		Yes/No
f)	Contraction Joints provided or not (CC Pavement)		Yes/No
g)	Compaction of flank/slope & raincuts if any		Yes/No/NA
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting		S/SRI/U SRI
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SRI/U NA
c)	Condition of railings/slab/approach for Bridges		S/SRI/U NA
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		Yes/No <input checked="" type="checkbox"/> NO
4.	Compliance History		
a)	Status of ATR's & any others		

Overall Rating :

Satisfactory (S)	—
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	—

18.12.2020  
(Signature)

NAME: Rana Baoun Kumar Singh

DESIGNATION: Executive Engineer

Scanned with CamScanner