

FIELD INSPECTION REPORT

Date of Inspection : 18.12.2020		District: NALANDA
Division : Raxi		Length (km): 0.950 km
Name of the Road: Kartayna Vikrajpur path, Sahibpur, Palatpur, Mirza, SCA of 1st		
Scheme/Programme: MAINTENANCE		New MR Maintenance policy 2018
Package No.:		Road Id No.:
Status of the Project:		Ongoing/Completed/Under Maintenance ✓
Work is a case of:		New Connectivity/Up gradation/ Maintenance ✓
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓S/U S
b)	Condition of Surfacing	✓S/U S
c)	Riding Quality	✓S/U S
d)	Road Camber	✓S/U S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	✓Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	—

Overall Rating :

Satisfactory (S)	✓ S
Satisfactory but requires Improvement (SRI)	—
Unsatisfactory (U)	—

(Signature) 18.12.2020

NAME: Rana Basim Kumar Singh

DESIGNATION: Executive Engineer

Scanned with CamScanner

Scanned with CamScanner