

FIELD INSPECTION REPORT


Date of Inspection : 17.12.2020		District : Bhagalpur
Division : Bhagalpur		Length (km) : 0.525
Name of Road : MMGSY Path (DEvNaryan Sthan to Tanti Tola) to Navtolia		
Scheme/Programme : NEW MAINTENANCE POLICY - 2018		
Package No. : 20		Road Id No.: 27321033883
Status of the Project :		
Work is a case of :		
Sl. No.	Particulars to be checked	Remarks
1	Pavement	
a)	Road Junction condition	NA
b)	Condition of Surfacing	NA
c)	Riding Quality	NA
d)	Road Camber	NA
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	NA
f)	Contraction Joints provided or not (CC Pavement)	NA
g)	Compaction of flank/slope & raincuts if any	NA
2	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	NA
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	NA
c)	Condition of railings/slab/approach for Bridges	NA
3	Road Furniture	
a)	Whether sign board/informatory/cautionary Board/km & 200m stones/Pavement Road marking are provided and Maintained	NA
4	Construction History	
a)	Status of ATR's & any others : Work under tender process	

Overall Rating :

Satisfactory (S)	NA
Satisfactory but requires Improvement (SRI)	NA
Unsatisfactory (U)	NA

NAME : KUMAR RAKESH

DESIGNATION : EXECUTIVE ENGINEER


 (Signature) 17.12.2020