## FIELD INSPECTION REPORT

	of Inspection: 18	XII 2022 District: West chambo	tan
Name	ion: R.WD(W) Se of the Road: DW	Length (km): 8.348	
		D ROAD TO CHANDRAHA MAINTENANCE	
Packa			00.9
Status	s of the Project:	BA6/19-0014 Road Id No.: 31890 1033 Ongoing/Completed/Under Maintenance	992
Work		New Connectivity/Up gradation/ Maintenance New	/ Maistake
Sl. No.		Parameters to be checked	Remarks
1.	Pavement		7.
a)	Road Junction condition		S/U
b)	Condition of Surfacing		S/U
c)	Riding Quality		S/U
d)	Road Camber		S/U
e)	Whether free from defects such as visible cracks, exposed		Yes/No
f)	Contraction Joints provided or not (CC Pavement)		Yes/No
g)	Compaction of flank/slope & raincuts if any		Yes/No
2.	Cross Drainage	44. 14. 14. 14. 14. 14. 14. 14. 14. 14.	1 3 3 7 1 0
a)	Condition of head walls in Hume pipe culverts including its painting S/SRI/U		
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SRI/U
c)	Condition of railings/slab/approach for Bridges		S/SRI/U
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		Yes/No
4.	Compliance Histor	<b>V</b>	Mary or assemble or a second
a)	Status of ATR's & any others		

Overall Rating

Satisfactory (S) Satisfactory but requires Improvement (SRI) Unsatisfactory (U)

Aggreement done work has not started Notice Issued NAME: - Ratnesh Parwan

DESIGNATION: Executive Engineer