

FIELD INSPECTION REPORT

Date of Inspection :	17.12.2020	District :	Munger
Division :	Munger	Length (Km) :	2.390 km
Name of the Road :	NH-80 Amaiya Se pipra path ka Dusra kilometer.		
Scheme/Programme :	MAINTENANCE HR(3054) old		
Package No. :		Road Id No. :	20803708148
Status of the Project :	Ongoing/Completed/Under Maintenance		
Work is a case of :	New Connectivity/Up gradation/Maintenance		
Sl. No.	Parameters to be checked	Remarks	
1	Pavement		
a)	Road Junction condition	W/U	
b)	Condition of Surfacing	S/U	Large pots filled with metal visible
c)	Riding Quality	S/U	See BT at several places.
d)	Road Camber	W/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	
g)	Compaction of flank/slope & raincuts if any	Yes/No	
2	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	NA
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	NA
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	NA
3	Road Furniture		
a)	Whether sign boards/informatory/cautionary board/Km & 200m stones/Pavement road markings are provided and maintained	Yes/No	
4	Compliance History		
a)	Status of ATR's & any others		

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	U

NAME : RAJIV RANJAN KUMAR
DESIGNATION : EE

(Signature) 17/12/2020