

FIELD INSPECTION REPORT

Date of Inspection : 18.12.2020	District: Nalanda
Division : Rajgry	Length (km): 5.7 km
Name of the Road: Varan to Koraipah via Gopaldhan Bridge	
Scheme/Programme: MAINTENANCE	New Maintenance Pk 2018 MK
Package No.:	Road Id No.:
Status of the Project: Ongoing/Completed/Under Maintenance	Ongoing
Work is a case of:	New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	—

MSS work done only, Surface SDB not done

Overall Rating :

NA

Satisfactory (S)	—
Satisfactory but requires Improvement (SRI)	—
Unsatisfactory (U)	—

18.12.2020
(Signature)

NAME: Rama Basan Kumar Singh

DESIGNATION: Executive Engineer