FIELD INSPECTION REPORT

Date of I	uspection : 17	12 2020	Districts NALDINDA			
Division: Ribarchail Length (km)1 2 60 km						
Name of	the Rond: Ele	no to sinakaus	Road	and the state of the state of		
Scheme/	Programmei	MAINTENANCE	mx-3034			
Package			Road Id No.:			
	the Projecti	Ongoing/Completed	Winder Maintenance			
Work is	n case of:	THE RESERVE OF THE PERSON NAMED IN COLUMN TWO IS NOT THE OWNER, THE PERSON NAMED IN COLUMN TWO IS NOT THE OWNER.	Up gradation/ Maintenance			
SL No.	Parameters to be checked			Remarks		
1.	Pavement					
n)	Road Junction condition			S/U U		
b)	Condition of Surfacing			S/UV		
c)	Riding Quality			S/U 5		
d)	Road Camber			S/U S		
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No M		
n	Contraction Joints provided or not (CC Pavement)			Yes/No//		
(g)	Compaction of flank/slope & raincuts If any			Yes/NoY4, NoT	minle	
2.5	Cross Drainage					
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/USR I		
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U NA		
c)	Condition of railings/slab/approach for Bridges			S/SRI/U NA		
, , · 3 . ; .	Road Furniture					
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No		
李沙	Compliance I	- 1				
a)	Status of ATR	L's & any others		-		

Overall Rating

Satisfactory (S)	1
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	U

(Signature)

NAME: Rana Bosom Kromar Singh DESIGNATION: Executive Enfire 4

Scanned with CamScanner