

FIELD INSPECTION REPORT

Date of Inspection : 18/12/2020	District: East Champaran	
Division : Motihari	Length (km): 4.61	
Name of the Road: NH 28 SE Machha	Vidyalay Sugaw - Bhigaw Ambekar Ayesh Mahadadi Tala - Vidyalay	
Scheme/Programme: MAINTENANCE		
Package No.: -	Road Id No.: 31708205002	
Status of the Project: Ongoing/Completed/Under Maintenance		
Work is a case of: New Connectivity/Up gradation/ Maintenance	New M/R	
SL No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No N/A
f)	Contraction Joints provided or not (CC Pavement)	Yes/No N/A
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U N/A
3.	Road Furniture	
a)	Whether sign boards informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	N/A

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

18/12/20
(Signature)

NAME: Bindu Rajak

DESIGNATION: Executive Engineer
R.W.D.
Regional Laboratory Darbhanga