

FIELD INSPECTION REPORT


| | | |
|---|--|--------------------------|
| Date of Inspection : 17.12.2020 | | District : Bhagalpur |
| Division : Bhagalpur | | Length (km) : 5.2 |
| Name of Road : Repair of road from Nathnagar N.H.-80 to Radhanagar (Part-A) | | |
| Scheme/Programme : OLD MAINTENANCE | | |
| Package No. : | | Road Id No.: 20703208220 |
| Status of the Project : Under Maintenance | | |
| Work is a case of : Maintenance | | |
| Sl. No. | Parameters to be checked | Remarks |
| 1 Pavement | | |
| a) | Road Junction condition | S |
| b) | Condition of Surfacing | S |
| c) | Riding Quality | S |
| d) | Road Camber | S |
| e) | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. | Yes |
| f) | Contraction Joints provided or not (CC Pavement) | Yes |
| g) | Compaction of flank/slope & raincuts if any | No. |
| 2 Road Drainage | | |
| a) | Condition of head walls in Hume pipe culverts including its painting | SRI |
| b) | Condition of Abutment & Wing walls, Slab in RCC culverts | SRI |
| c) | Condition of railings/slab/approach for Bridges | SRI |
| 3 Road Markings | | |
| a) | Whether sign board/informatory/cautionary Board/km & 200m stones/Pavement Road marking are provided and Maintained | Yes |
| 4 Compliance History | | |
| a) | Status of ATR's & any others : Under Five Year Maintenance | |

Overall Rating :

| | |
|---|-----|
| Satisfactory (S) | |
| Satisfactory but requires Improvement (SRI) | SRI |
| Unsatisfactory (U) | |

NAME : KUMAR RAKESH

DESIGNATION : EXECUTIVE ENGINEER


 (Signature) 17.12.2020