

FIELD INSPECTION REPORT

Date of Inspection : 17.12.2020		District : Bhagalpur
Division : Bhagalpur		Length (km) : 10.22
Name of Road : Repair of road from Nathnagar Tamtam Stand to Kajrauli		
Scheme/Programme : OLD MAINTENANCE		
Package No. :		Road Id No.: 20703208223
Status of the Project : Under Maintenance		
Work is a case of :		
Sl. No.	Parameters to be checked	Remarks
1 Pavement		
a)	Road Junction condition	S
b)	Condition of Surfacing	S
c)	Riding Quality	S
d)	Road Camber	S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	No.
f)	Contraction Joints provided or not (CC Pavement)	Yes
g)	Compaction of flank/slope & raincuts if any	No.
2 Culvert/Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	NA
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	NA
c)	Condition of railings/slab/approach for Bridges	NA
3 Road Furniture		
a)	Whether sign board/informatory/cautionary Board/km & 200m stones/Pavement Road marking are provided and Maintained	Yes
4 Compliance History		
a)	Status of ATR's & any others : Work has not been started	

Overall Rating :

Satisfactory (S)	NA
Satisfactory but requires Improvement (SRI)	NA
Unsatisfactory (U)	NA

NAME : KUMAR RAKESH

DESIGNATION : EXECUTIVE ENGINEER

(Signature) 17.12.2020