

# FIELD INSPECTION REPORT

Date of Inspection : 18.12.2020		District: NALANDA
Division : Rajgir		Length (km): 5.100 Km
Name of the Road: Repair of Road from Durgapur Chaurak to Sakul Midgachai via Karna Village		
Scheme/Programme: MAINTENANCE		MR-3054
Package No.:		Road Id No.:
Status of the Project:	Ongoing/Completed/Under Maintenance ✓	
Work is a case of:	New Connectivity/Up gradation/ Maintenance ✓	
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U U
b)	Condition of Surfacing	S/U U
c)	Riding Quality	S/U U
d)	Road Camber	S/U S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No -
g)	Compaction of flank/slope & raincuts if any	Yes/No Yes
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U No
c)	Condition of railings/slab/approach for Bridges	S/SRI/U No
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No No
4.	Compliance History	
a)	Status of ATR's & any others	-

Overall Rating :

Satisfactory (S)	—
Satisfactory but requires Improvement (SRI)	—
Unsatisfactory (U)	U

(Signature)  
18.12.2020

NAME: Rama Baroun Kr. Singh  
DESIGNATION: Executive Engineer.

Scanned with CamScanner