


# FIELD INSPECTION REPORT

Date of Inspection : 18.12.2020		District: NALANDA	
Division : Rajgir		Length (km): 0.990 km	
Name of the Road: NH 31 Se purwaha to kark purh Nyma kary			
Scheme/Programme: MAINTENANCE		MD-3054	
Package No.:		Road Id No.:	
Status of the Project:		Ongoing/Completed/Under Maintenance <input checked="" type="checkbox"/>	
Work is a case of:		New Connectivity/Up gradation/ Maintenance <input checked="" type="checkbox"/>	
Sl. No.	Parameters to be checked		Remarks
1.	Pavement		
a)	Road Junction condition		S/U U
b)	Condition of Surfacing		S/U U
c)	Riding Quality		S/U U
d)	Road Camber		S/U S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	NA
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	NA
g)	Compaction of flank/slope & raincuts if any	Yes/No	NO
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	N.A
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	N.A
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No	NO
4.	Compliance History		
a)	Status of ATR's & any others		

Overall Rating :

Satisfactory (S)	<input checked="" type="checkbox"/>
Satisfactory but requires Improvement (SRI)	<input type="checkbox"/>
Unsatisfactory (U)	<input type="checkbox"/>

  
18.12.2020  
(Signature)

NAME: Rama Baroun K. Singh

DESIGNATION: Executive Engineer

Scanned with CamScanner