

FIELD INSPECTION REPORT

Date of Inspection : 18/12/20	District: Saharsa
Division : Saharsa	Length (km): 10.42 KM
Name of the Road: SH-59 Bhaupiya More to Samda Tilaha Bridge	
Scheme/Programme:	MAINTENANCE
Package No.:	Road Id No.: 20904308100
Status of the Project:	Ongoing/Completed/Under Maintenance
Work is a case of:	New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓S/U
b)	Condition of Surfacing	S/✓U
c)	Riding Quality	S/✓U
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	✓Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ✓
4.	Compliance History	
a)	Status of ATR's & any others	

N.A. Old C.C. pavement

N.A. Old culvert not painted

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	U

Ashok
(Signature) 18/12/20

NAME: ASHOK KUMAR

DESIGNATION: Executive Engineer