

### FIELD INSPECTION REPORT

Date of Inspection : 18/11/2020		District: West Champaran
Division : R.W.D (N) Div. Bagh-1		Length (km): 5.7
Name of the Road: Repair of road from P.W.D ROAD NARWAL to Khatiya		
Scheme/Programme: MAINTENANCE		
Package No.: .	Road Id No.: 31869008078	
Status of the Project:	Ongoing/Completed/Under Maintenance MR/3654	
Work is a case of:	New Connectivity/Up gradation/ Maintenance	

  

Sl. No.	Parameters to be checked	Remarks
1.	<b>Pavement</b>	
a)	Road Junction condition — S	S/U
b)	Condition of Surfacing — partially pot develop in B.T portion	S/U
c)	Riding Quality — S	S/U
d)	Road Camber — S	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. yes	Yes/No
f)	Contraction Joints provided or not (CC Pavement) — yes	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	<b>Cross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its painting SRI	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	<b>Road Furniture</b>	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained yes	Yes/No
4.	<b>Compliance History</b>	
a)	Status of ATR's & any others — NU	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

NAME: Ratnesh Paswan  
DESIGNATION: Executive Engineer

21/11/2020  
(Signature) 18/12/2020