

FIELD INSPECTION REPORT


Date of Inspection : 17.12.2020		District : Bhagalpur
Division : Bhagalpur		Length (km) : 1.8
Name of Road : Raghupur to Shahpur Pul Tak		
Scheme/Programme : OLD MAINTENANCE		
Package No. :		Road Id No.: 20703200840
Status of the Project : Under Maintenance		
Work is a case of :		
Sl. No.	Parameters to be checked	Remarks
1. Pavement		
a)	Road Junction condition	S
b)	Condition of Surfacing	S
c)	Riding Quality	S
d)	Road Camber	S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes
f)	Contraction Joints provided or not (CC Pavement)	Yes
g)	Compaction of flank/slope & raincuts if any	NO.
2. Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	SRI
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	SRI
c)	Condition of railings/slab/approach for Bridges	SRI
3. Road Pavement		
a)	Whether sign board/informatory/cautionary Board/km & 200m stones/Pavement Road marking are provided and Maintained	Yes
4. Land/Border History		
a)	Status of ATR's & any others : Work under Five Year Maintenance	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

NAME : KUMAR RAKESH

DESIGNATION : EXECUTIVE ENGINEER


 (Signature) 17.12.2020