

FIELD INSPECTION REPORT

Date of Inspection : 17.12.2020		District: NALANDA	
Division : Rihassan't		Length (km): 1.640 km	
Name of the Road: Gopaldhara - Kotoa (Miyabur) Path to Rupadpur Path			
Scheme/Programme:		MAINTENANCE MR-3054	
Package No.:		Road ID No.:	
Status of the Project:		Ongoing/Completed/Under Maintenance ✓	
Work is a case of:		New Connectivity/Up gradation/ Maintenance ✓	
Sl. No.	Parameters to be checked		Remarks
1.	Pavement		
a)	Road Junction condition		✓S/U S
b)	Condition of Surfacing		✓S/U S
c)	Riding Quality		✓S/U S
d)	Road Camber		✓S/U S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		✓Yes/No/y/n
f)	Contraction Joints provided or not (CC Pavement)		✓Yes/No/y/n
g)	Compaction of flank/slope & raincuts if any		✓Yes/No/y/n Notrained
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting		✓S/SRI/U S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		✓S/SRI/U S
c)	Condition of railings/slab/approach for Bridges		S/SRI/U NA
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		✓Yes/No y/n
4.	Compliance History		
a)	Status of ATR's & any others		—

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	—
Unsatisfactory (U)	—

(Signature)
17.12.2020

NAME: Rama Basma Kumar Singh

DESIGNATION: Executive Engineer

Scanned with CamScanner

Scanned with CamScanner