

# FIELD INSPECTION REPORT

Date of Inspection : 18/12/2020	District: Chaya
Division : Shergathi	Length (km): 2.20 km
Name of the Road: GT Road to Elja	
Scheme/Programme: MAINTENANCE	NEWS
Package No.:	Road Id No.:
Status of the Project: <input checked="" type="checkbox"/> Ongoing <input type="checkbox"/> Completed <input type="checkbox"/> Under Maintenance	
Work is a case of: New Connectivity Up gradation Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	<b>Pavement</b>	
a)	Road Junction condition	✓S/U
b)	Condition of Surfacing	✓S/U
c)	Riding Quality	✓S/U
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	NA Yes/No
f)	Contraction Joints provided or not (CC Pavement)	NA Yes/No
g)	Compaction of flank/slope & raincuts if any	✓Yes/No raincuts.
2.	<b>Cross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its painting	NA SRI
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	NA S SRI/U
c)	Condition of railings/slab/approach - Bridges	NA S/SRI/U
3.	<b>Road Furniture</b>	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	sign board Yes/No work in progress
4.	<b>Compliance History</b>	
a)	Status of ATR's & any others	NA

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

37  
18/12/2020  
(Signature)

NAME: Srikant Prasad.

DESIGNATION: E.E