## FIELD INSPECTION REPORT

Date of	Inspection: \	8/12/2020	District: Crayo	हुको क्षावादी संस्था देश हो। एक वर्षां वेशकाला क्षावादा का स्थापना हो। यह स्थापना है । यह स्थापना है एक वर्षाण
Division: Sherghali Name of the Road: Gaya Dobhi W			Length (km): 1.50Km	
Name of	f the Road: 🖎	aya Dobhi	wikilgan to Migara.	or the state of th
Scheme	/Programme:	MAINTENAN	Road Id No.:	ngayay ar senten didahilikat arasi, kada senting <b>300,000 Bad di</b> sama dalah kelajah dalah
Package No.:			mpleted/Under Maintenance	
The second secon	f the Project:	New Connectiv	ity/Up gradation/ Maintenance	and the first time to the property of the state of the st
Work is a case of:		Parameters to be checked Re		Remarks
1.	Payement			
A STATE OF THE STA	Road Junction condition			√S/U
a)				√S/U
b)	Condition of Surfacing			
c)	Riding Quality			<b>\\$</b> 7U
d)	Road Camber			✓ <b>S</b> /U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			
f)	The state of the s			HAYes/No
g)	Compaction of flank/slope & raincuts if any were in progress MAYes/No			
2.	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting NA S/SRI/U			
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			
c)				S/SRI/U
3.	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m yes/Nostones/Pavement road markings are provided and maintained			
4.	Compliance History			
a)	Status of ATR's & any others			No

Overall Rating :

Satisfactory (S)	\$.
Satisfactory but requires Improvement (SRI)	Note the control of t
Unsatisfactory (U)	enter de de service de l'activité qualitaire de la company

(Signature)

NAME: 30 Kant Frank

DESIGNATION: EE